





Centauri Carbon 3D Printer
Update firmware tutorial

Contents

Method 1: USB Disk Update.....1

Method 2: OTA Update.....5

Method 1: USB Disk Update




I. Copy and paste the downloaded firmware into the USB drive

Note:


1. The firmware name should be lowercase 'update', please do not rename it
2. Do not have files with the same name as the firmware on the USB drive

Method 1: USB Disk Update



II. Turn on the machine and insert the USB flash drive into it


Method 1: USB Disk Update



III.3、 Click on "System" → "Settings" → "Check for Updates" in sequence

*There is a red dot in the upper right corner of the "Check for Updates" version number, indicating that there are available updates


Method 1: USB Disk Update



IV. Click here to select update to new version

*After the update is complete, the machine will automatically restart, After restarting, if prompted to update, there is no need to update again. Just confirm if the version number is the latest

Method 2: OTA Update



I. When a new version is available, the latest version information announcement will pop up after booting up. Click on update to update.


*After the update is complete, the machine will automatically restart. If the version number becomes the latest, then the upgrade is successful.

Method 2: OTA Update

Q&A:

Q: Why doesn't my machine display a new version update announcement?

A: Please check if the machine is properly connected to the network. The new version cannot be detected when it is not connected to the network.




Method 2: OTA Update

Q: The new version update announcement pops up very slowly.

A: Depending on the network conditions, there may be a delay of 1-3 seconds when an update announcement pops up after booting up.

Q: If you accidentally click cancel, will the update still be displayed next time you restart?

A: After clicking cancel, a new version update notification will still pop up the next time you restart. You can also directly click "System" -> "Settings" -> "Detect Update" on the display screen and click on the version number to update.



Method 2: OTA Update

Q: What should I do if the version update fails due to poor network signal, connection timeout, or abnormal connection during the process?

A: It may be caused by poor network environment or unstable connection for a short period of time. You can try to update again by restarting the machine after the network condition is restored or stabilized.

